

PORSCHE

P323

914

PA SERVICE MANAGER

PRODUCT INFORMATION CIRCULAR

- 1) PAIR OF GEARS - 5th SPEED
Parts Identifier 323 95

FEBRUARY 24, 1972

Manufacturing tolerances are so close that the gears do not require any pairing. This means, they are interchangeable.

In case of repair, however, the gears have to be replaced as a set of two, because a used gear cannot be matched with a new one.

This does not apply for 911 gears. (Product Information Circular P 323/911 of February 17, 1972)