

PORSCHE

P323

914

PRODUCT INFORMATION CIRCULAR

SYNCHRONIZER MECHANISM
PARTS IDENTIFIER # 323 31/32/37/39

August 15, 1972

It is essential that in case of a repair or replacement of the Synchronizer Mechanism on Porsche 914 transmissions, the energizer, brake bands and stop, are to be replaced as a set.

Should it become necessary to replace the Synchronizer ring Part # 911 302 301 02 the following parts must be replaced in conjunction:

1 Energizer	Part # 911 302 315 00
2 Brake bands	Part # 911 302 316 00
1 Stop	Part # 911 302 317 01