

# PORSCHE

# P740

# 914

## PRODUCT INFORMATION CIRCULAR

Air Conditioner, Complete - Hoses  
Parts Identifier 740 01

June 12, 1973

Whenever it becomes necessary to repair air conditioner hoses, repair kits are available from Volkswagen Product Corporation as announced in

VW Parts Circular # 158/72 October 2, 1972

In order to repair, simply cut out the defective section of the hose, insert the tube, and secure the hose with clamps. Recharge the system.