

# PORSCHE

# P90

914

## PRODUCT INFORMATION CIRCULAR

SPEEDOMETER  
Part Identifier 90 06

---

September 30, 1975

Inaccurate speedometer readings or noise necessitates proper diagnosis:

- a. Check speedometer cable for proper routing.
- b. If routing is correct but noise or inaccuracy still exists, replace cable.

IMPORTANT: Do not lubricate cable because lubricant will be drawn into speedometer, causing inaccurate reading.