
PORSCHE

Product Circular

Group
914 26

November 8, 1976

Subject:

Catalytic Converter
Part Identifier 26 73

Key Points:

Disconnecting catalytic converter maintenance
reminder light - 1975 and 1976 model

CALIFORNIA ONLY

Replacing catalytic converter as
part of 30,000 mile maintenance
is no longer necessary for 914 -
2.0 ltr. 1975-1976 model.

Therefore, CAT maintenance reminder
light has to be disconnected.

Work sequence

- locate multi-pin plug on elapsed
mileage odometer
- cut both blue-yellow wires going
into plug
- strip ends and splice both wires
together and insulate